

Air Check Oxygen monitor with remote Horn & Strobe




Air check Oxygen Monitor
Digital gas concentration display
Two User selectable Alarm relays
Alarm 2 amp 30 VAC / 240 VAC
One System Fault relay 2amp 30 VAC / 240 VAC
Built-in visual alarm LED's
24VDC powered 500mA
4-20mA analog output
Wall mounted enclosure

Remote Horn & Strobe
Federal Signal
Voltage 18-30VDC, Current .068 Amp

Interference-Reducing Audio Cable, Plenum, 18/2 AWG, 0.17" OD, 300 VAC, Off-White, 250'L
McMaster Carr p/n 71055K76



Remote Display



Supervised 4-20mA output to PLC

Power supply
p/n T1073-P5P-ND



PureAire
monitoring systems, inc.